

**PlenumS-CUTT-170-WW**

Cutting Tool for PlenumShield Armored 1/2" ClearFill®Line Aluminum Plenum-Rated Air-Dielectric Coaxial Cable

Cutting Tool for PlenumShield Armored ClearFill®Line 1/2" low-loss air dielectric cable

FEATURES / BENEFITS

- **PlenumShield Armored Cable Solution Cutting Tool.**
- **Flexibility and adaptability for intricate installations.**
- **Enhanced safety and efficiency with PlenumShield technology.**



PlenumS-CUTT-170-WW

Technical features**APPLICATIONS**

Applications		PlenumShield to JBox	In Building	DAS	NFPA 72 section 12.4.2 Pathway Survivability Level 1
--------------	--	----------------------	-------------	-----	--


STRUCTURE

Cable Type		PlenumShield, Air-Dielectric, Corrugated, Armored Cable
------------	--	---

TESTING AND ENVIRONMENTAL

Regulatory Compliance		NFPA 72 section 12.4.2 Pathway Survivability Level 1
-----------------------	--	--

- 1 REMOVE lock nut
 - 2 LOOSEN UP the screw on top of the locking double bite piece
 - 3 INSERT the PlenumShield™ cable
 - 4 TIGHTEN UP the screw on top of the locking double bite piece to secure the cable
 - 5 INSERT fitting into the box
 - 6 INSERT lock nut to fitting to secure to the box
- NOTE *Angle Connectors are not recommended.



External Document Links

Notes